




**Instruction Manual**  
**3-in-1 E Tester**  
**Model: N73BZ**





### Features

- 3½ digit (2000 count) LCD display
- Built-in non-contact AC voltage detector plus flashlight
- Double moulded housing
- CATIII 1000V
- 200mA/500V resettable fused current inputs and overload protection on all ranges
- Autoranging with auto power off

### Safety

#### International Safety Symbols



This symbol, adjacent to another symbol or terminal, indicates the user must refer to the manual for further information.



This symbol, adjacent to a terminal, indicates that, under normal use, hazardous voltages may be present.



Double insulation

#### Safety Precautions


1. Improper use of this meter can cause damage, shock, injury or death. Read and understand this users manual before operating the meter.
2. Make sure any covers or battery doors are properly closed and secured.
3. Always disconnect the test leads from any voltage source before replacing the battery or fuses.
4. Do not exceed the maximum rated input limits.

Function	Input Limits	
	Maximum Input	
V DC or V AC	600V DC/AC	
µA, mA AC/DC	200mA/500V fast acting resettable fuse	
Resistance, diode & continuity test	600V DC/AC	

5. Use great care when making measurements if the voltages are greater than 25Vac rms or 35Vdc. These voltages are considered a shock hazard.
6. Always discharge capacitors and remove power from the device under test before performing diode, resistance or continuity tests.
7. Remove the battery from the meter if the meter is to be stored for long periods.

**Meter Description**

1. Non-contact AC voltage detector probe tip
2. Non-contact AC voltage indicator light
3. 3½ Digit (2000 count)
4. MODE button
5. Function switch
6. Flashlight
7. Flashlight button
8. Data Hold button
9. Battery cover
10. Test leads



### Specifications

#### Electrical Specifications:

Function	Range	Accuracy
DC Voltage	200mV	$\pm(0.5\% \text{ rdg} + 3\text{d})$
	2V, 20V, 200V, 600V	$\pm(1.2\% \text{ rdg} + 3\text{d})$
AC Voltage 40-400Hz	2V, 20V	$\pm(1.0\% \text{ rdg} + 8\text{d})$
	200V, 600V	$\pm(2.3\% \text{ rdg} + 10\text{d})$
DC Current	200 $\mu$ A, 2000 $\mu$ A	$\pm(2.0\% \text{ rdg} + 8\text{d})$
	20mA, 200mA	
AC Current	200 $\mu$ A, 2000 $\mu$ A	$\pm(2.5\% \text{ rdg} + 10\text{d})$
	20mA, 200mA	
Resistance	200 $\Omega$	$\pm(0.8\% \text{ rdg} + 5\text{d})$
	2k $\Omega$ , 20k $\Omega$ , 200k $\Omega$	$\pm(1.2\% \text{ rdg} + 5\text{d})$
	2M $\Omega$	$\pm(5.0\% \text{ rdg} + 5\text{d})$
	20M $\Omega$	$\pm(10.0\% \text{ rdg} + 5\text{d})$

**Max input voltage:** 600V AC/DC  
**Diode test:** Test current 1mA max., open circuit voltage of 1.5V typical  
**Continuity check:** Audible signal if the resistance is <150 $\Omega$   
**Display:** 2000 count 3½ digit LCD  
**Over range indication:** LCD displays "OL"  
**Polarity:** Minus (-) sign for negative polarity.  
**Low battery indication:** "BAT" symbol indicates low battery condition  
**Input Impedance:** >7.5M $\Omega$  (Vdc & Vac)  
**AC Response:** Average responding  
**ACV Bandwidth:** 50Hz to 400Hz  
**Auto power off:** 15 minutes (approximately)  
**Fuse:** mA,  $\mu$ A ranges; 0.2A/500V fast acting resettable fuse

**Batteries:** Two 1.5V AAA  
**Operating Temperature:** 0°C to 40°C (32°F to 104°F)  
**Storage Temperature:** -10°C to 50°C (14°F to 122°F)  
**Weight:** 145g  
**Size:** 104 x 55 x 32,5mm  
**Standard:** IEC61010 CAT III 1000V Pollution degree II, CE Approved

### **Operation**

---

#### **AC/DC VOLTAGE MEASUREMENTS**

**CAUTION:** Do not measure AC/ DC voltages if a motor on the circuit to be measured is being switched ON or OFF. Large voltage surges may occur that can damage the meter.

1. Set the function switch to the green V position.
2. Press the MODE button to indicate "DC" or "AC" on the display.
3. Place the black test probe tip to the negative side of the circuit.  
Place the red test probe tip to the positive side of the circuit.
4. Read the voltage in the display

#### **DC/AC CURRENT MEASUREMENTS**

1. Set the function switch to the  $\mu\text{A}/\text{mA}$  position.
2. For current measurements up to 2000 $\mu\text{A}$  DC/AC, set the function switch to the **mA** position
3. Press the MODE button to indicate "DC" / "AC" on the display.
4. Remove power from the circuit under test, then open up the circuit at the point where you wish to measure current.
5. Place the black test probe tip to the negative side of the circuit.  
Place the red test probe tip to the positive side of the circuit.
6. Apply power to the circuit.
7. Read the current in the display

**NOTE:** 0.2A/500V fast acting resettable fuse current inputs and overload protection on mA,  $\mu$ A ranges. No replacement required.

#### RESISTANCE MEASUREMENT

**WARNING:** To avoid electric shock, disconnect power to the unit under test and discharge all capacitors before taking any resistance measurements. Remove the batteries and unplug the line cords.

1. Set the function switch to the  $\Omega$   $\rightarrow$   $\rightarrow$  position.
2. Press the MODE button to indicate  $\Omega$  on the display.
3. Place the test probe tips across the circuit or part under test. It is best to disconnect one side of the part under test so the rest of the circuit will not interfere with the resistance reading.
4. Read the resistance in the display

#### CONTINUITY CHECK

**WARNING:** To avoid electric shock, never measure continuity on circuits or wires that have voltage on them.

1. Set the function switch to the  $\Omega$   $\rightarrow$   $\rightarrow$  position.
2. Press the MODE button to indicate  $\rightarrow$  on the display
3. Touch the test probe tips to the circuit or wire you wish to check.
4. If the resistance is less than approximately  $150\Omega$ , the meter will beep. If the circuit is open, the display will indicate "OL".

#### DIODE TEST

1. Set the function switch to the  $\Omega$   $\rightarrow$   $\rightarrow$  position.
2. Press the MODE button to indicate  $\rightarrow$  on the display.
3. Touch the test probes to the diode under test. Forward voltage will typically indicate 0.4 to 0.7V. Reverse voltage will indicate "OL". Shorted devices will indicate near 0V and an open device will indicate "OL" in both polarities

#### Non-Contact AC Voltage Measurements:

**WARNING:** Risk of electrocution. Before use, always test the voltage detector on a known live circuit to verify proper operation

1. Hold the probe tip near to the electrical supply.
2. If AC voltage is present, the detector light will illuminate.

**NOTE:** Electrical cable often gets twisted. For best results, rub the probe tip along a length of the cable to ensure the tip is close to the live conductor.

**NOTE:** The detector is highly sensitive. Static electricity or other sources of energy may randomly trip the sensor. This is normal.

#### Hold Button

The Data Hold function allows the meter to "freeze" a measurement for later reference

1. Press the **"DATA HOLD"** button to "freeze" the display, the **"HOLD"** indicator will appear.
2. Press the **"DATA HOLD"** button to return to normal operation.

#### Flashlight

Press and hold the top button to turn the flashlight on. Release the button to turn the flashlight off.

#### AUTO POWER OFF

The auto off feature will turn the meter off after 15 minutes.



**REPLACING THE BATTERY**

1. Undo the screw and remove the bottom cover.
2. Replace the old batteries with 2 new 1.5V AAA batteries (Order Code L42AL).
3. Replace the bottom cover and tighten the screw.

**REPLACING THE FUSE**

1. Disconnect the test leads from the meter.
2. Remove the test leads holder and top cover screw.
3. Lift the center circuit board straight up from the connectors to gain access to the fuse holders.
4. Remove the old fuse and place the new fuse into the holder.
5. Always use a fuse of the proper size and value (0.2A/250V fast blow for the 200mA range).
6. Align the center board with the connectors and gently press into place.
7. Replace and secure the rear cover and screw.

**WARNING:** To avoid electric shock, do not operate your meter until the fuse cover is in place and fastened securely.





#### Notice to customers



This symbol on the battery indicates that the battery is to be collected separately. The following apply only to users in European countries.

- This battery is designed for separate collection at an appropriate collection point. Do not dispose of as household waste
- For more information, contact the retailer or local authorities in charge of waste management.



Maplin Electronics Ltd  
Brookfields Way, Manvers  
Wath-Upon-Dearne  
Rotherham, S63 5DL  
[www.maplin.co.uk](http://www.maplin.co.uk)