

ATTENTION:

GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2010~11MY Legacy; 2009~10MY Tribeca;
 2008~11MY Impreza STI;
 2008 & 2011MY Impreza
SUBJECT: Service Manual Corrections

NUMBER: 18-151-10
DATE: 10/15/10

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, updated service manual information.

MODEL	YEAR	STIS PUBLICATION NUMBER	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
Impreza	2011	G1100BE	Engine (H4SO)(diag)	EN(H4SO)(diag)-243	Diagnostic steps changed for P0852.
		G1100BE	Chassis	WT-3,4,9	Figure and specification updates.
	2008	L1940BE	Body Repair Manual	BS-47,48	Body sealing diagrams updated/changed.
Impreza STI	2011	G1100BE	Chassis	WT-3,4,8	Figure and specification updates.
	2010	G1990BE	6MT	6MT(diag)-9	DCCD I/O Chart changed and updated.
	2009	G1970BE	6MT	6MT(diag)-9	DCCD I/O Chart changed and updated.
	2008	G1950BE	6MT	6MT(diag)-9	DCCD I/O Chart changed and updated.
Legacy	2011	G2470BE	Transmission	6MT-84	Reverse Gear Installation steps updated/changed.
	2010	G2460BE	Transmission	6MT-82	Reverse Gear Installation steps updated/changed.
			Chassis	RS-4	Rear Subframe tightening torque updated/changed.
		Body	GW-56	Inspection notes added.	
			IDI-18	Checks for the Clock updated/changed.	
SL-11,12,73-78	Checks for the Door Locks updated/changed.				
Tribeca	2010	G3150BE	Transmission	5AT(diag)-41,45,88	Diagnostic steps for P0715, P0720 & P1710 are changed.
	2009	G3140BE	Transmission	5AT(diag)-41,46,89	Diagnostic steps for P0715, P0720 & P1710 are changed.